




A x 1	F12656			G11 x 10	FG0011
C x 2	PI1733			H1 x 14	FH0001
F x 1	ZO0533			H14 x 1	FH0014
G x 2	AN0388			H15 x 48	FH0015
H x 2	CS0493			M22 x 6	FM0022
O x 2	SH0561			R3 x 2	FR0003
Q x 1	QH0007			V5 x 12	FV0005
Z x 1	FI2657			V25 x 12	FV0025
W x 2	OF0029			V45 x 10	FV0045
				B9 x 6	FB0009
				C1 x 6	FC0001
				W93 x 1	FW0093
				A1 x 2	FA0001

QF0636




3




B9=6




A1=2




R3=2



A1 sx




Z




R3

A
Z



A1 sx



A1 dx




A



B9

A






A1 dx

A

4

C1=6

V5=12




5

V45=10




G11=10




6

H15=48






H15

90°



7



8

W93=1

M22=2

V25=4

